

Calibration Instruction



for

Personnel Grounding Tester PGT®130.DT with Calibration Unit

Page 1 / 7 V10/2021



Allgemeines

The calibration unit contains resistors for Personal-Grounding-Tester PGT[®] 130.DT**PGT130.DT** verification. It works without battery or any external power supply.

The calibration is performed in measure mode, to measure the test voltage an additional DC-voltmeter is required.

Important: Remove all connections from the measuring inputs of the PGT® 130.DT!

Open Calibration Menu

Info: This option can be disabled via web interface settings [Device settings – Config buttons]



Press the left button for at least 3 seconds



Keep the left button pressed and tap the right button at least 4 times back-to-back

The device switches to configuration mode. The configuration mode will time-out automatically after 5 minutes without operation, settings will be stored.

Browse through the parameter menu with the left button until CALIBRATION




Page 2 / 7 V10/2021



Test Voltage Measurement

To check the PGT[®] 130.DT **PGT130.DT** test voltage set the marked lever of the rotary switch to position **V** and connect:

- the blue socket of the Calibration Unit with the blue [CAL] 4mm socket of the PGT® 130.DT
- the black socket of the Calibration Unit with the black 4 mm socket for wrist strap test of the PGT®130.DT



Use a DC-voltmeter with an impedance Ri ≥ 10MΩ, preferably measuring range 3V.

Connect the socket of the Calibration Unit additionally with the voltage input of the voltmeter.

The test voltage of the voltmeter is read in factor 1:100. $(100V \Rightarrow 1,00V)$

Compare the displayed values with the measurements of the voltmeter.

Admissible deviation: ±5%

Example: For 100V measuring voltage the instrument must display a value between 0,95V and 1,05V.


Page 3 / 7 V10/2021



Wrist strap verification

To check the limits of the wrist strap test connect:

- the blue socket of the Calibration Unit with the blue [CAL] 4mm socket of the PGT® 130.DT.
- the black socket of the Calibration Unit with the black 4 mm socket for wrist strap test of the PGT[®] 130.DT



Set the marked lever of the rotary switch in succession to the positions mentioned below and read the displayed values.

| Switch position | Set-point | Display |
|-----------------|------------|---------|
| 100k | 100 kΩ | |
| ∞ | disconnect | |
| 20M | 20 ΜΩ | |
| ∞ | disconnect | |
| 40M | 40 ΜΩ | |
| ∞ | disconnect | |
| 200M | 200 ΜΩ | |

Admissible deviation: ±5%


Page 4 / 7 V10/2021



Footwear test verification - shoe left

To check the limits of the footwear test connect:

- the blue socket of the Calibration Unit with the blue [CAL] 4mm socket of the PGT® 130.DT.
- the black socket of the Calibration Unit with the black 4 mm socket of the PGT® 130.DT shoe left.



Set the marked lever of the rotary switch in succession to the positions mentioned below and read the displayed values.

| Switch position | Set-point | Display |
|-----------------|------------|---------|
| 100k | 100 kΩ | |
| ∞ | disconnect | |
| 10M | 10 ΜΩ | |
| ∞ | disconnect | |
| 20M | 20 ΜΩ | |
| ∞ | disconnect | |
| 200M | 200 ΜΩ | |

Admissible deviation: ±5%


Page 5 / 7 V10/2021



Footwear test verification - shoe right

To check the limits of the footwear test connect:

- the blue socket of the Calibration Unit with the blue [CAL] 4mm socket of the PGT® 130.DT.
- the black socket of the Calibration Unit with the red 4 mm socket of the PGT® 130.DT shoe right.



Set the marked lever of the rotary switch in succession to the positions mentioned below and read the displayed values.

| Switch position | Set-point | Display |
|-----------------|------------|---------|
| 100k | 100 kΩ | |
| ∞ | disconnect | |
| 10M | 10 ΜΩ | |
| ∞ | disconnect | |
| 20M | 20 ΜΩ | |
| ∞ | disconnect | |
| 200M | 200 ΜΩ | |

Admissible deviation: ±5%

Page 6 / 6 V10/2021